

GRAPHIC INSTALLATION TIPS

GRAPHIC INSTALLATION TIPS

STEP 1

PREP SURFACE Make sure the surface you are applying to is clean. Remove any existing adhesive on the surface with adhesive remover. Clean the surface one last time with rubbing alcohol or glass cleaner.


STEP 2

POSITION GRAPHIC Place graphics in position desired making sure the decal is flat. Tape at corner with masking tape to hold decal in place. Run a long piece of tape vertically through the center of the decal to act as a hinge.



STEP 3

APPLY GRAPHIC Swing one edge of the decal away from the application surface & remove backing paper up to the tape hinge. Cut the backing paper next to the hinge using a single sided blade.



STEP 4

APPLY GRAPHIC Swing the decal back into the original position but do not let adhesive touch surface. Using firm overlapping strokes with a squeegee, start at hinge edge & squeegee decal into place being careful not to trap air.



STEP 5

REPEAT

Remove tape hinge & repeat steps 3, 4, & 5 for the other side of the decal. Re squeegee the entire decal.

STEP 5

REMOVE PREMASK Remove the white premask tape from the face of the decal by slowly peeling back at 180 degrees. You can go over the decal with a heat gun, or hair dryer and gently rub them down one more time. Be careful not to overheat the graphics.